5 Wiring diagrams

5 - 1 Wiring Diagrams - Single Phase

MCK55W



H1O	BUZZER 1 (RECEIVING SIGN)	BS1	MAIN SWITCH	H8P	LED(ON/OFF:GREEN)	H20P	LED(ODOUR SIGN:RED/GREEN)	M1F	FAN MOTOR
A1P	PRINTED CIRCUIT BOARD(FOR DISPLAY)	BS2	HUMIDIFICATION SWITCH	H9P	LED(CHILD PROOF LOCK:ORANGE)	H21P	LED(HUM MONITOR 30%:BLUE)	M1	STEPPER MOTOR(FOR HUMIDIFYING GEAR)
A2P	PRINTED CIRCUIT BOARD(FOR CONTROL)	BS3	AIRFLOW SWITCH	H10P	LED(HUM ON/OFF:ORANGE)	H22P	LED(HUM MONITOR 40%:BLUE)	K1A	LIMIT SWITCH
A3P	PRINTED CIRCUIT BOARD(FOR POWER SUPPLY)	H1P	LED(QUIET:GREEN)	H11P	LED(AUTO FAN:GREEN)	H23P	LED(HUM MONITOR 50%:BLUE)	S1L	FLOAT SWITCH
A4P	PRINTED CIRCUIT BOARD (HIGH VOLTAGE POWER SUPPLY FOR IONISATION)	H2P	LED(L:GREEN)	H12P	LED(ECONO:GREEN)	H24P	LED(HUM MONITOR 60%:BLUE)	Z1C	FERRITE CORE
A5P	PRINTED CIRCUIT BOARD(FOR HUMIDITY SENSOR)	H3P	LED(S:GREEN)	H13P	LED(ANTI-POLLEN:GREEN)	H25P	LED(HUM MONITOR 70%:BLUE)	X1P	POWER SUPPLY PLUG
A6P	PRINTED CIRCUIT BOARD(FOR DUST SENSOR)	H4P	LED(TURBO:GREEN)	H14P	LED(MOIST:GREEN)	H26P	LED(STREAMER LAMP:BLUE)		
A7P	PRINTED CIRCUIT BOARD(FOR ODOUR SENSOR)	H5P	LED(HUM L:GREEN)	H17P	LED(WATER SUPPLY:RED)	F1U	FUSE(250V, 3.15A)		
A8P	PRINTED CIRCUIT BOARD(FOR HIGH VOLTAGE POWER SUPPLY)	H6P	LED(HUM S:GREEN)	H18P	LED(DUST SIGN:RED/GREEN)				
S1NG	ODOUR SENSOR	H7P	LED(HUM H:GREEN)	H19P	LED(PM2.5 SIGN:RED/GREEN)				

3D106488D