

Discontinuation of inlet grille on EDLA/EBLA 4/6/8 and ERGA 4/6/8

March 2026

This briefing explains a design update affecting certain Daikin Altherma outdoor units, including EDLA 4/6/8 and EBLA 4/6/8 monobloc models, and ERGA 4/6/8 refrigerant split systems.

Background

As part of ongoing product development, the inlet grille has been removed from these models to align with the wider Daikin Altherma outdoor unit range.

Affected products

Monobloc outdoor units:

EDLA04EV3

EDLA06EV3

EDLA08EV3

EBLA04EV3

EBLA06EV3

EBLA08EV3

Refrigerant-split outdoor units:

ERGA04EVA

ERGA06EVA

ERGA08EVA



Product changes

The inlet metal grille covering the evaporator has been removed from the Daikin Altherma residential outdoor units listed above. The grille previously formed a metal mesh across the full height and width of the evaporator.

Market feedback identified that small debris, such as leaves or litter, could pass through the grille openings and become trapped between the grille and the heat exchanger. In some cases, this could restrict airflow, which may reduce operating efficiency and affect long-term performance. Under certain weather conditions, ice can also form on the grille, further restricting airflow and affecting performance.

The inlet grille has been removed as part of a design update to the outdoor unit.



Outdoor units, with and without the inlet grilles

The grille has now been removed from all products using the small cabinet. This change aligns the whole range of Daikin Altherma outdoor units. Larger products in the Daikin Altherma range, including the EDLA monobloc, ERLA refrigerant split and EPRA HHT hydrosplit outdoor units, already operate without this grille. This update therefore brings the smaller models into line with the wider Altherma range.

This change also aligns with the whole range of Residential A2A outdoor units with the same case, including Multi+.

Quotations and Price

Material codes and product pricing remain unchanged.

Stock

Units manufactured from November 2025 onwards are supplied without the metal inlet grille.

Deliveries and Warranty

The grille is not a missing component, its removal is part of the updated product design. The grille cannot be retrofitted to units supplied without it, as the revised design does not include mounting points. As with similar Daikin Altherma product ranges, the grille is not being made available as an optional accessory.

For further information
please contact your sales representative