


7 Wiring diagrams

7 - 1 Wiring Diagrams - Single Phase



CN, CN1, S16~920, FG	Connector
X1M	Terminal block
F1U	Fuse (T, 3.15A, 250V)
M1F	Motor (indoor fan)
M1~3S	Motor (swing flap)
M4S	Motor (front panel)
A1~7P	Printed circuit
R1T, R2T	Thermistor
IES	Intelligent eye sensor
BS1, BS2	Button switch
H1~3P	Pilot lamp
SR	Signal receiver
H1O	Buzzer
S1RH	Humidity sensor
Z1C, Z2C, Z3C	Ferrite core
E1	Heat exchanger
K1R	Magnetic relay
V1R	Rectifier
C101, C102	Capacitor
TC	Transmission circuit
⊕	Protective earth
R1V	Varistor

 : Field wiring

WIRE COLORS

BLK : Black
YLW : Yellow
RED : Red
BLU : Blue
BRW : Brown
WHT : White

CAUTION

- When the main power is turned off and then back on again, operation will resume automatically.

3D113338D