


8 Wiring diagrams


8 - 1 Wiring Diagrams - Single Phase

RXM50A



3D130906A

RXM60-71A



3D150217